



MCMIS

Motor Carrier Management
Information System

View Inspection Report

[Location/Activities](#) |
 [Company](#) |
 [Driver/Shipper](#) |
 [Vehicle/Hm](#) |
 [Violations](#) |
 [Shipper Viols](#) |
 [Special Studies](#) |
 [Show All](#)

Report State:		Report Number:		Report Status:	
USDOT#:		Company Type:		Company Status:	
Company Name:					

Location Details							
Report Number:							
Inspection Date:	03/25/2011	Start Time:	11:32	End Time:	11:47	Inspection Level:	3 - DRIVER-ONLY INSPECTION
Location Description:	LULA SCALE US 49	Location Code:	B-94	County State:	MS	County Code:	027 - COAHOMA
Facility Type:	F	Inspector ID:	B00051	Service Center:	SH		

Special Activities			
Alcohol/Controlled Substance Check:	N	Traffic Enforcement:	N
Conducted by Local Jurisdiction:	N	Drug Interdiction Search:	N
Size and Weight Enforcement:	N	Post-Crash Inspection:	N
Was the Inspection conducted as part of a PASA (Pre Authority Safety Audit)?			
Was a Performance Based Brake Test (PBBT) performed?			
Number of axles on the vehicle used in the PBBT:		PBBT Type of Vehicle:	
Vehicle Brake Force:		Minimum required Brake Force Required to pass PBBT:	

Uploaded/Calculated Fields			
SAFETYNET Version:	3.10.1.0	SAFETYNET Search date:	
PEN Version:	2.12	PEN Cen Match:	
Transaction Code:	A		
Transaction Date:	03/25/2011	Upload Date:	09/12/2011
MCMIS Add Date:	09/13/2011	Final Status Date:	09/13/2011

Uploaded Carrier Fields			
USDOT#:		State Census Number:	
Company Name:			
Street Address:			
Colonia:			
City:		State:	

			ZIP/Postal Code:
Interstate:	Y	Service Center:	SH
Census Source Code:	P PEN-BASED (NOT USED ON CRASHES)	Upload Search Indicator:	
Certification:			

Driver Identification			
Last Name:		First Name:	
Middle Initial:		Date of Birth:	
License Number:		License State/Country:	

Shipper Identification			
Shipper Name:		Paper Number:	11055

Vehicle Information (Units)								
Unit	Type	Make	Year	Company#	License#	State	VIN	Weight Rating
1	TRUCK TRACTOR	VOLV	2001					1
	CVSA Decal Issued?	Decal#	Existing Decal#	Decal Status	Out-of-Service Sticker#			
	NO			NONE				
	Removed Cargo Seal ID				Replaced Cargo Seal ID			
Unit	Type	Make	Year	Company#	License#	State	VIN	Weight Rating
2	SEMI-TRAILER	HMDE	1999					0
	CVSA Decal Issued?	Decal#	Existing Decal#	Decal Status	Out-of-Service Sticker#			
	NO			NONE				
	Removed Cargo Seal ID				Replaced Cargo Seal ID			

Gross Combined Vehicle Weight	0
-------------------------------	---

Hazardous Materials Information

There is no hazardous materials information for this inspection.

Violations

There are no violations on this inspection

Motor Carrier Violation Summaries					
Total Violations	0	Total Motor Carrier Violations	0	Total Driver Violations	0
Total OOS Violations	0	Total Motor Carrier OOS Violations	0	Total Driver OOS Violations	0

Shipper Info (Violations)

There are no shipper violations for this inspection